

**Flood Control Project Maintenance
Levee Inspections**

2019 Channel Summary Report

Overall Unit and Item Ratings

DWR Sutter Maintenance Yard

Big Chico Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Lindo Channel & Sandy Gulch

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Little Chico Creek

Overall Unit Rating	Rated Item	Item Rating
M *	Vegetation & Obstructions	M *
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

Flood Control Project Maintenance**Unit Cover Sheet****2019 Channel Inspection Results****DWR Sutter Maintenance Yard**

Channel
Big Chico Creek

Channel Rating	A
Date of Inspection	7/9/2019
DWR Inspector	Sterling York
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Big Chico Creek Control Structure / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_1			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_5_1_20190715_00030.jpg



View of the channel from the structure facing upstream from the structure, 2019.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_3			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Big Chico Creek Control Structure / Up (cont)

Rating **	A	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_4			

Action/Comments

Inspector Comments: Some of the riprap is covered with vegetation. Trees and other vegetation growth should be managed/removed from riprap.

Photo 1 of 1 : CH_2019_NA0060_5_4_20190701_00002.jpg



View of typical revetment on the upstream side of the structure, 2017.

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_5			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Big Chico Creek Control Structure / Down

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_6			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_5_6_20190715_00033.jpg



View of the downstream side of the channel from the structure, 2019.

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_8			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Big Chico Creek Control Structure / Down (cont)

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_9			
Action/Comments				
Inspector Comments: Riprap is visible and appears properly maintained.				

Photo 1 of 2 : CH_2019_NA0060_5_9_20190715_00032.jpg



View of the revetment downstream right bank of the channel from the structure, 2019.

Rating **	A	Issue No.	9 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_9			

Photo 2 of 2 : CH_2019_NA0060_5_9_20190715_00031.jpg



View of the revetment downstream left bank of the channel from the structure, 2019.

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c _ 2012_10			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Manzanita Ave. / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c _ 2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_5_11_20190715_00034.jpg



This photo is looking upstream from under Manzanita Avenue Bridge, 2019.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c _ 2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation was observed.				

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c _ 2012_14			
Action/Comments				
Inspector Comments: Riprap is visible and appears properly maintained.				

Photo 1 of 2 : CH_2019_NA0060_5_14_20190715_00036.jpg



View looking upstream at the right bank of typical revetment around the abutment and bike path, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Manzanita Ave. / Up (cont)

Rating **	A	Issue No.	14 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_14			

Action/Comments

Inspector Comments: Riprap is visible and appears properly maintained.

Photo 2 of 2 : CH_2019_NA0060_5_14_20190715_00035.jpg



View looking upstream at the left bank of typical revetment around the abutment and bike path, 2019.

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_15			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Manzanita Ave. / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_16			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_5_16_20190715_00037.jpg



This photo is looking downstream from Manzanita Avenue Bridge, 2019.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c _ 2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_18			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Manzanita Ave. / Down (cont)

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_19			

Action/Comments

Inspector Comments: Riprap is visible and appears properly maintained.

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_20			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View


Hwy 99 Bridge / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_21			

Action/Comments

Inspector Comments: Minimal scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 1 : CH_2019_NA0060_5_21_20190715_00038.jpg



View of the channel up from Highway 99 facing upstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Hwy 99 Bridge / Up (cont)

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_22			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_23			
Action/Comments				
Inspector Comments: No erosion present.				

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_24			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap is clearly visible on both sides.				

Photo 1 of 2 : CH_2019_NA0060_5_24_20190715_00040.jpg



View of revetment along the channel right bank, looking upstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Hwy 99 Bridge / Up (cont)

Rating **	A	Issue No.	24 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_24			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap is clearly visible on both sides.				

Photo 2 of 2 : CH_2019_NA0060_5_24_20190715_00039.jpg



View of revetment along the channel left bank, looking upstream, 2019.

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_25			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Hwy 99 Bridge / Down

Rating **	M	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_26			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation, the flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_5_26_20190715_00041.jpg



View of the channel under Highway 99 facing downstream, 2019.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_28			
Action/Comments				
Inspector Comments: No erosion present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Hwy 99 Bridge / Down (cont)

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_29			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap is clearly visible on both sides.				

Photo 1 of 1 : CH_2019_NA0060_5_29_20190701_00015.jpg



View of the type of riprap that lines the channel, 2018.

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_30			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Esplanade / Up

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_36			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_5_36_20190715_00045.jpg



View of the channel facing upstream, 2019.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_33			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Esplanade / Up (cont)

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_34			
Action/Comments				
Inspector Comments: No revetments present.				

Photo 1 of 2 : CH_2019_NA0060_5_34_20190715_00046.jpg



No visible revetment right bank, 2019.

Photo 2 of 2 : CH_2019_NA0060_5_34_20190715_00047.jpg



No visible revetment left bank, 2019.

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_35			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard


Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Esplanade / Down

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_31			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation is minimal. The flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_5_31_20190715_00044.jpg



View of the channel facing downstream, 2019.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_37			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_38			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Esplanade / Down (cont)

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_39			
Action/Comments				
Inspector Comments: No revetments present.				

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c _ 2012_40			
Action/Comments				
Inspector Comments: Old bridge footings are within the project easement area, flow is not impeded, 2019.				

Photo 1 of 1 : CH_2019_NA0060_5_40_20190701_00020.jpg



View of old bridge footing in the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Hwy 32 / Up

Rating **	A	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_41			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_5_41_20190715_00048.jpg



View of the channel facing upstream, 2019.

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_42			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_43			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Hwy 32 / Up (cont)				
Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c _ 2012_44			
Action/Comments				
Inspector Comments: Revetments present both sides of channel.				

Photo 1 of 1 : CH_2019_NA0060_5_44_20190715_00050.jpg



View of revetment around piers both right bank and left bank, 2019.

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c _ 2012_45			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Hwy 32 / Down

Rating **	M	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_46			
Action/Comments				
Inspector Comments: Moderate vegetation on banks. The flow may be impeded.				

Photo 1 of 1 : CH_2019_NA0060_5_46_20190715_00051.jpg



View of the channel facing downstream, 2019.

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_47			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_48			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Hwy 32 / Down (cont)				
Rating **	A	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_49			
Action/Comments				
Inspector Comments: Revetments present on both sides.				

No Photos

Check Point / View				
Mud Creek at River Rd / Up				
Rating **	A	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580°
Category	Rivers, Channels & Designated Flood			-121.939320°
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_51			
Action/Comments				
Inspector Comments: Minimal scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_5_51_20190715_00052.jpg



View of Mud Creek at River Road facing upstream, 2019.

Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_52			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Mud Creek at River Rd / Up (cont)

Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_58			

Action/Comments

Inspector Comments: No erosion observed.

No Photos

Rating **	A	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_54			

Action/Comments

Inspector Comments: Riprap is covered with vegetation. Trees and other vegetation growth should be managed/removed from riprap.

Photo 1 of 2 : CH_2019_NA0060_5_54_20190715_00057.jpg



View of the revetment right bank that is over grown with vegetation, 2019.

Rating **	A	Issue No.	54 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_54			

Photo 2 of 2 : CH_2019_NA0060_5_54_20190715_00056.jpg



View of the revetment left bank that is over grown with vegetation, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Mud Creek at River Rd / Up (cont)

Rating **	A	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_55			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Mud Creek at River Rd / Down

Rating **	A	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_56			

Action/Comments

Inspector Comments: No obstructions observed, the flow is not impeded.

Photo 1 of 1 : CH_2019_NA0060_5_56_20190715_00053.jpg



View looking downstream from the bridge, 2019.

Rating **	A	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_57			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Mud Creek at River Rd / Down (cont)

Rating **	A	Issue No.	53	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c _ 2012_53			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	A	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c _ 2012_59			
Action/Comments				
Inspector Comments: Some of the riprap is covered with vegetation. Trees and other vegetation growth should be managed/removed from riprap.				

No Photos

Rating **	A	Issue No.	60	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c _ 2012_60			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2019 Channel Inspection Results****DWR Sutter Maintenance Yard**

Channel
Lindo Channel & Sandy Gulch

Channel Rating	A
Date of Inspection	7/9/2019
DWR Inspector	Sterling York
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Diversion Structure / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_1			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and small trees exists however the flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_1_20190715_00063.jpg



View of the channel facing upstream, 2019.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_3			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Diversion Structure / Up (cont)

Rating **	N	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_4			

Action/Comments

Inspector Comments: No revetment at the upstream of the structure.

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_5			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Diversion Structure / Down

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_6			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.

Photo 1 of 1 : CH_2019_NA0060_6_6_20190715_00064.jpg



View of the channel facing downstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Diversion Structure / Down (cont)

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_8			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_9			
Action/Comments				
Inspector Comments: Revetment observed at this location is intact, clearly visible, and well maintained.				

Photo 1 of 2 : CH_2019_NA0060_6_9_20190715_00065.jpg



View of revetment downstream of structure, right bank, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Diversion Structure / Down (cont)

Rating **	A	Issue No.	9 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_9			

Action/Comments

Inspector Comments: Revetment observed at this location is intact, clearly visible, and well maintained.

Photo 2 of 2 : CH_2019_NA0060_6_9_20190715_00066.jpg



View of revetment downstream of structure, left bank, 2019.

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c _ 2012_10			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Manzanita Ave / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_11_20190715_00067.jpg



View of the channel facing upstream, 2019.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_12			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_13			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Manzanita Ave / Up (cont)

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_14			

Action/Comments

Inspector Comments: Revetment under bridge, both right and left abutments.

Photo 1 of 2 : CH_2019_NA0060_6_14_20190715_00069.jpg



View of revetment right bank at bridge abutment, 2019.

Rating **	A	Issue No.	14 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_14			

Photo 2 of 2 : CH_2019_NA0060_6_14_20190715_00070.jpg



View of revetment left bank at bridge abutment, 2019.

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c _ 2012_15			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Manzanita Ave / Down

Rating **	M	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_16			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists and the flow could be impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_16_20190715_00068.jpg



View of the channel facing downstream, 2019.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_18			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Manzanita Ave / Down (cont)

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_19			

Action/Comments

Inspector Comments: Revetment under bridge, both right and left abutments.

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_20			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Bike Path Bridge at Madrone Ave / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_21			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.

Photo 1 of 1 : CH_2019_NA0060_6_21_20190715_00071.jpg



View of the channel facing upstream from the bridge, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Bike Path Bridge at Madrone Ave / Up (cont)

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_22			

Action/Comments

Inspector Comments: Minimal shoaling or sedimentation observed.

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_23			

Action/Comments

Inspector Comments: No head cutting or horizontal deviation observed.

No Photos

Rating **	M	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_24			

Action/Comments

Inspector Comments: Riprap at the foot of the bridge seems to have slid down towards the channel in previous high water events, but the capacity of the channel is not affected.

Photo 1 of 2 : CH_2019_NA0060_6_24_20190715_00073.jpg



View looking at the right bank abutment very little revetment remaining, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Bike Path Bridge at Madrone Ave / Up (cont)

Rating **	M	Issue No.	24 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_24			

Action/Comments

Inspector Comments: Riprap at the foot of the bridge seems to have slid down towards the channel in previous high water events, but the capacity of the channel is not affected.

Photo 2 of 2 : CH_2019_NA0060_6_24_20190715_00072.jpg



View looking at the left bank abutment very little revetment remaining, 2019.

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_25			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Bike Path Bridge at Madrone Ave / Down

Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c _ 2012_26			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_26_20190715_00074.jpg



View of the channel facing downstream from the bridge, 2019.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c _2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c _ 2012_28			
Action/Comments				
Inspector Comments: There is some minor bank erosion.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Bike Path Bridge at Madrone Ave / Down (cont)

Rating **	N	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_29			
Action/Comments				

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c _ 2012_30			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View

Mariposa Ave / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_31			
Action/Comments				
Inspector Comments: Minimal, scattered log obstructions exists however the flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_31_20190715_00075.jpg



View of the channel facing upstream from the bridge, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Mariposa Ave / Up (cont)				
Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_32			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c _ 2012_33			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_34			
Action/Comments				
Inspector Comments: Revetment on slope up to the bridge abutment, both sides.				

Photo 1 of 2 : CH_2019_NA0060_6_34_20190715_00077.jpg



View of right bank, revetment on slope up to the bridge abutment, 2019.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Mariposa Ave / Up (cont)

Rating **	A	Issue No.	34 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_34			

Action/Comments

Inspector Comments: Revetment on slope up to the bridge abutment, both sides.

Photo 2 of 2 : CH_2019_NA0060_6_34_20190715_00076.jpg



View of left bank, revetment on slope up to the bridge abutment, 2019.

Rating **	M	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_35			

Action/Comments

Inspector Comments: Debris present within the project easement area needs to be removed from pilings, 2019.

Photo 1 of 1 : CH_2019_NA0060_6_35_20190715_00080.jpg



View of debris present within the project easement area that needs to be removed from pilings, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Mariposa Ave / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_36			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_36_20190715_00078.jpg



View of the channel facing downstream from the bridge, 2019.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c _ 2012_37			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed, but the flow is not impeded.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_38			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Mariposa Ave / Down (cont)				
Rating **	A	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_39			
Action/Comments				
Inspector Comments: Revetment on slope up to the bridge abutment, both sides.				

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_40			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
5th Ave / Up				
Rating **	A	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_41			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_41_20190715_00079.jpg



View of the channel facing upstream from the bridge, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
5th Ave / Up (cont)				
Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_42			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed, but doesn't impede the flow of the channel.				

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_43			
Action/Comments				
Inspector Comments: No erosion present on the upstream end.				

No Photos

Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_44			
Action/Comments				
Inspector Comments: Existing riprap protecting is properly maintained and is undamaged. There is erosion at the toe on left bank abutment.				

Photo 1 of 2 : CH_2019_NA0060_6_44_20190715_00082.jpg



View of right bank, revetment on slope up to the bridge abutment, 2019.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
5th Ave / Up (cont)				
Rating **	A	Issue No.	44 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_44			
Action/Comments				
Inspector Comments: Existing riprap protecting is properly maintained and is undamaged. There is erosion at the toe on left bank abutment.				

Photo 2 of 2 : CH_2019_NA0060_6_44_20190715_00083.jpg



View of left bank, revetment on slope up to the bridge abutment, 2019.

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c _ 2012_45			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

5th Ave / Down

Rating **	A	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_46			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_46_20190715_00084.jpg



View of channel facing downstream from the bridge, 2019.

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_47			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation present, but the flow is not impeded.				

No Photos

Rating **	M	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_48			
Action/Comments				
Inspector Comments: There is erosion around bridge footing and south bank of channel.				

Photo 1 of 1 : CH_2019_NA0060_6_48_20190715_00081.jpg



View of the erosion found under the bridge south end left bank, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
5th Ave / Down (cont)				
Rating **	A	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_49			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		39.753307 °
Category	Rivers, Channels & Designated Flood			-121.829234 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_50			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Highway 99 / Up				
Rating **	A	Issue No.	91	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2015_91			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_91_20190715_00085.jpg



View of the channel facing upstream from the channel, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Highway 99 / Up (cont)				
Rating **	A	Issue No.	92	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2015_92			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	93	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c _ 2015_93			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	99	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2015_99			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible both sides.				

Photo 1 of 2 : CH_2019_NA0060_6_99_20190715_00086.jpg



View of right bank revetment looking upstream on slope up to the bridge abutment, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Highway 99 / Up (cont)

Rating **	A	Issue No.	99 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2015_99			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible both sides.				

Photo 2 of 2 : CH_2019_NA0060_6_99_20190715_00087.jpg



View of left bank revetment looking upstream on slope up to the bridge abutment, 2019.

Rating **	A	Issue No.	95	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c _ 2015_95			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Highway 99 / Down

Rating **	A	Issue No.	96	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2015_96			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_96_20190715_00088.jpg



View of the channel facing downstream from under the north bound lanes of Highway 99, 2019.

Rating **	A	Issue No.	97	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c _ 2015_97			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	98	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c _ 2015_98			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Highway 99 / Down (cont)

Rating **	A	Issue No.	94	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2015_94			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

Rating **	A	Issue No.	100	GPS Lat/Long
Issue Type +	Ma	Location *		39.751220 °
Category	Rivers, Channels & Designated Flood			-121.840042 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2015_100			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View

Mangrove Avenue / Up

Rating **	A	Issue No.	111	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2015_111			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_111_20190715_00090.jpg



View of the channel looking upstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Mangrove Avenue / Up (cont)				
Rating **	A	Issue No.	112	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2015_112			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

No Photos

Rating **	A	Issue No.	113	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c _ 2015_113			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	114	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2015_114			
Action/Comments				
Inspector Comments: No visible revetment observed.				

Photo 1 of 1 : CH_2019_NA0060_6_114_20190701_00058.jpg



View looking upstream at the right bank abutment, no revetment observed, 2018.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard


Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Mangrove Avenue / Up (cont)				
Rating **	A	Issue No.	115	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2015_115			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Mangrove Avenue / Down				
Rating **	M	Issue No.	116	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2015_116			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation exists which may impede the flow of the channel.				

Photo 1 of 1 : CH_2019_NA0060_6_116_20190715_00091.jpg



View of the channel facing downstream, 2019.

Rating **	A	Issue No.	117	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2015_117			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Mangrove Avenue / Down (cont)

Rating **	A	Issue No.	118	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2015_118			

Action/Comments

Inspector Comments: No head cutting or horizontal deviation observed.

No Photos

Rating **	N	Issue No.	119	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2015_119			

Action/Comments

Inspector Comments: No visible revetment observed.

Photo 1 of 1 : CH_2019_NA0060_6_119_20190701_00061.jpg



View looking downstream at the right bank abutment, no revetment observed, 2018.

Rating **	A	Issue No.	120	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2015_120			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Esplanade / Up

Rating **	M	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_51			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists and the flow could be impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_51_20190715_00094.jpg



View of the channel facing upstream, 2019.

Rating **	A	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_57			
Action/Comments				
Inspector Comments: Shoaling present on the upstream side underneath the bike crossing bridge, but it doesn't affect the channel capacity.				

No Photos

Rating **	A	Issue No.	53	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_53			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank that would endanger the capacity of the channel was observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Esplanade / Up (cont)

Rating **	N	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_54			

Action/Comments

Inspector Comments: There is no revetment at the bridge abutments and is not needed.

Rating **	N	Issue No.	54 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_54			

Rating **	N	Issue No.	54 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_54			

Photo 1 of 3 : CH_2019_NA0060_6_54_20190715_00097.jpg



View of the right abutment, no revetment exist, 2019.

Photo 2 of 3 : CH_2019_NA0060_6_54_20190715_00096.jpg



View of the left abutment, no revetment exist, 2019.

Photo 3 of 3 : CH_2019_NA0060_6_54_20190715_00095.jpg



View of the left bank revetment next to the abutment, there is no revetment in the channel at the abutment, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Esplanade / Up (cont)

Rating **	M	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_55			

Action/Comments

Inspector Comments: Debris is caught on the foot bridge piles and needs to be removed, 2019.

Photo 1 of 2 : CH_2019_NA0060_6_55_20190715_00093.jpg



View of the channel facing upstream. The debris is caught on the foot bridge piles, 2019.

Rating **	M	Issue No.	55 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_55			

Photo 2 of 2 : CH_2019_NA0060_6_55_20190715_00092.jpg



Closer view of debris caught in and around the foot bridge upstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Esplanade / Down

Rating **	M	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_56			
Action/Comments				
Inspector Comments: Vegetation and scattered obstructions exists and the flow may be impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_56_20190715_00098.jpg



View of the channel facing downstream, 2019.

Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2013_52			
Action/Comments				
Inspector Comments: Minimal shoaling and sedimentation present.				

No Photos

Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_58			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank that would endanger the capacity of the channel was observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Esplanade / Down (cont)				
Rating **	N	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_59			
Action/Comments				
Inspector Comments: There is no revetment in the channel at the abutments.				

Photo 1 of 1 : CH_2019_NA0060_6_59_20190701_00034.jpg



View of the right bank looking downstream, there is no revetment in the channel at the abutment, 2018.

Rating **	A	Issue No.	60	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_60			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Holly Avenue / Up

Rating **	A	Issue No.	101	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2015_101			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation exists however the flow does not look to be impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_101_20190715_00099.jpg



View of the channel looking upstream, 2019.

Rating **	A	Issue No.	102	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_102			
Action/Comments				
Inspector Comments: Minimal shoaling and sedimentation present.				

No Photos

Rating **	A	Issue No.	103	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_103			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Holly Avenue / Up (cont)

Rating **	A	Issue No.	104	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2015_104			

Action/Comments

Inspector Comments: Gabion wall revetment at bridge abutment, right and left bank.

Photo 1 of 2 : CH_2019_NA0060_6_104_20190715_00101.jpg



View of gabion wall revetment at bridge abutment, left bank, 2019.

Photo 2 of 2 : CH_2019_NA0060_6_104_20190715_00100.jpg



View of gabion wall revetment at bridge abutment, right bank, 2019.

Rating **	A	Issue No.	105	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c _ 2015_105			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Holly Avenue / Down

Rating **	A	Issue No.	106	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2015_106			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow does not seem to be impeded.				

Photo 1 of 1 : CH_2019_NA0060_6_106_20190715_00102.jpg



View of the channel looking downstream, 2019.

Rating **	A	Issue No.	107	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2015_107			
Action/Comments				
Inspector Comments: Minimal shoaling and sedimentation present.				

No Photos

Rating **	A	Issue No.	108	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2015_108			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Holly Avenue / Down (cont)				
Rating **	A	Issue No.	109	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2015_109			
Action/Comments				
Inspector Comments: Gabion wall revetment at bridge abutment, right and left bank.				

No Photos

Rating **	A	Issue No.	110	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2015_110			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Hwy 32 / Up				
Rating **	M	Issue No.	61	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_61			
Action/Comments				
Inspector Comments: Vegetation exists and may impede the flow.				

Photo 1 of 1 : CH_2019_NA0060_6_61_20190715_00103.jpg



View of the channel looking upstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Hwy 32 / Up (cont)				
Rating **	A	Issue No.	62	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_62			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	63	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_63			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	64	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_64			
Action/Comments				
Inspector Comments: Revetment is present and in good condition, but maintain vegetation to keep revetment visible.				

Photo 1 of 2 : CH_2019_NA0060_6_64_20190715_00105.jpg



View of right bank concrete filled sandbag revetment, typical for both sides, 2019.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Hwy 32 / Up (cont)

Rating **	A	Issue No.	64 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_64			
Action/Comments				
Inspector Comments: Revetment is present and in good condition, but maintain vegetation to keep revetment visible.				

Photo 2 of 2 : CH_2019_NA0060_6_64_20190715_00104.jpg



View of left bank concrete filled sandbag revetment, typical for both sides, 2019.

Check Point / View

Hwy 32 / Down

Rating **	M	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_66			
Action/Comments				
Inspector Comments: Vegetation exists and may impede the flow.				

Photo 1 of 1 : CH_2019_NA0060_6_66_20190715_00106.jpg



View of the channel looking downstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Hwy 32 / Down (cont)				
Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c _ 2012_67			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c _ 2012_68			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

No Photos

Rating **	A	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_69			
Action/Comments				
Inspector Comments: Revetment is present on left and right bank abutments.				

No Photos

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Hwy 32 / Down (cont)				
Rating **	A	Issue No.	70	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_70			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Oak Ave. / Up				
Rating **	M	Issue No.	121	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2017_121			
Action/Comments				
Inspector Comments: Various scattered obstructions or vegetation exists which may impede flows.				

Photo 1 of 1 : CH_2019_NA0060_6_121_20190715_00107.jpg



View of the vegetation looking upstream from the bridge, 2019.

Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_72			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Oak Ave. / Up (cont)				
Rating **	A	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_73			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_74			
Action/Comments				
Inspector Comments: No revetments present.				

Photo 1 of 2 : CH_2019_NA0060_6_74_20190715_00109.jpg



View of right abutment with no revetment, 2019.

Rating **	N	Issue No.	74 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_74			

Photo 2 of 2 : CH_2019_NA0060_6_74_20190715_00110.jpg



View of left abutment with no revetment, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Oak Ave. / Up (cont)				
Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_75			
Action/Comments				
Inspector Comments: No encroachments in the channel.				

No Photos

Check Point / View				
Oak Ave. / Down				
Rating **	M	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_71			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation exists which may impede the flow of the channel.				

Photo 1 of 1 : CH_2019_NA0060_6_71_20190715_00111.jpg



View of the channel facing downstream, 2019.

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_77			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Oak Ave. / Down (cont)

Rating **	A	Issue No.	78	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c _ 2012_78			

Action/Comments

Inspector Comments: No head cutting or horizontal deviation observed.

No Photos

Rating **	N	Issue No.	79	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_79			

Action/Comments

Inspector Comments: No revetments present.

No Photos

Rating **	A	Issue No.	80	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c _ 2012_80			

Action/Comments

Inspector Comments: No encroachments are visible in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard


Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Grape Way / Up

Rating **	M	Issue No.	81	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_81			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation exists and the flows may be impeded in the channel.				

Photo 1 of 1 : CH_2019_NA0060_6_81_20190715_00112.jpg



View of the channel facing upstream, 2019.

Rating **	A	Issue No.	82	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_82			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	83	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_83			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Grape Way / Up (cont)

Rating **	A	Issue No.	84	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_84			
Action/Comments				
Inspector Comments: Revetments are in place and maintained properly. Concrete sandbag revetment at bridge abutments, both sides.				

Photo 1 of 2 : CH_2019_NA0060_6_84_20190715_00115.jpg



View of concrete sandbag revetment at bridge abutments, right bank, 2019.

Rating **	A	Issue No.	84 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_84			

Photo 2 of 2 : CH_2019_NA0060_6_84_20190715_00114.jpg



View of concrete sandbag revetment at bridge abutments, left bank, 2019.

Rating **	A	Issue No.	85	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_85			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View

Grape Way / Down

Rating **	A	Issue No.	86	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_86			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation exists however the flows are not impeded in the channel.				

Photo 1 of 1 : CH_2019_NA0060_6_86_20190715_00113.jpg



View of the channel facing downstream, 2019.

Rating **	A	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_87			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	88	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_88			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/09/2019 07/09/2019	Sterling York

Check Point / View				
Grape Way / Down (cont)				
Rating **	A	Issue No.	89	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_89			
Action/Comments				
Inspector Comments: Revetments are in place and maintained properly. Concrete sandbag revetment at bridge abutments, both sides.				

No Photos

Rating **	A	Issue No.	90	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_90			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance
Unit Cover Sheet
2019 Channel Inspection Results

DWR Sutter Maintenance Yard

Channel
Little Chico Creek

Channel Rating	M *
Date of Inspection	7/2/2019
DWR Inspector	Sterling York
Accompanied By	

* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Little Chico Ck Control Structure / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_1			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2019_NA0060_12_1_20190710_00046.jpg



This is the upstream view from the Little Chico Weir, 2019.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_2			
Action/Comments				
Inspector Comments: There is a no shoaling and sedimentation, the flow is not impeded.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_3			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Little Chico Ck Control Structure / Up (cont)

Rating **	N	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2013_4			

Action/Comments

Inspector Comments: No revetment.

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_5			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Little Chico Ck Control Structure / Down

Rating **	M	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_6			

Action/Comments

Inspector Comments: Scattered obstructions and vegetation. The flow may be impeded. Willow trees should be removed.

Photo 1 of 1 : CH_2019_NA0060_12_6_20190701_00002.jpg



This is the downstream view from the Little Chico Control Structure, 2018.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Little Chico Ck Control Stucture / Down (cont)

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_7			
Action/Comments				
Inspector Comments: There is no shoaling and sedimentation, the flow is not impeded.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_8			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_9			
Action/Comments				
Inspector Comments: No revetment.				

No Photos

* Location

LS : Land Side
WS : Water Side
CR : Crown

** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Little Chico Ck Control Structure / Down (cont)

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_10			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Bruce Rd / Up

Rating **	A	Issue No.	114	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2019_114			

Action/Comments

Inspector Comments: The vegetation overhangs the channel but does not appear to impede the flows.

Photo 1 of 1 : CH_2019_NA0060_12_114_20190710_00050.jpg



View looking upstream from the bridge of the overhanging vegetation, 2019.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_12			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Bruce Rd / Up (cont)

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_13			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	N	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_14			
Action/Comments				
Inspector Comments: No revetments present.				

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_15			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions observed within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Bruce Rd / Down

Rating **	U	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_11			
Action/Comments				
Inspector Comments: The vegetation obstructed the view of the channel. Flow may be impeded in a high water event.				

Photo 1 of 1 : CH_2019_NA0060_12_11_20190805_00093.jpg



View of the channel facing downstream, 2019.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_18			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Bruce Rd / Down (cont)

Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_19			

Action/Comments

Inspector Comments: No revetments present.

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_20			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions observed within the project easement area.

No Photos

Check Point / View

Forest Ave / Up

Rating **	A	Issue No.	115	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2019_115			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 1 : CH_2019_NA0060_12_115_20190710_00051.jpg



View looking upstream at the channel from the bridge, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Forest Ave / Up (cont)

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_22			

Action/Comments

Inspector Comments: Shoaling or sedimentation present, the flow is not impeded.

No Photos

Rating **	M	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_23			

Action/Comments

Inspector Comments: Moderate erosion on north bank.

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_24			

Action/Comments

Inspector Comments: Revetments present.

Photo 1 of 2 : CH_2019_NA0060_12_24_20190710_00052.jpg



View of revetment on right bank, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Forest Ave / Up (cont)

Rating **	A	Issue No.	24 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_24			

Action/Comments

Inspector Comments: Revetments present.

Photo 2 of 2 : CH_2019_NA0060_12_24_20190710_00053.jpg



View of revetment on left bank, 2019.

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_25			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Forest Ave / Down

Rating **	M	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_21			
Action/Comments				
Inspector Comments: Scattered bushes and vegetation may impede the flow of the channel.				

Photo 1 of 1 : CH_2019_NA0060_12_21_20190710_00049.jpg



View of the channel from the bridge facing downstream, 2019.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present, the flow does not appear impeded.				

No Photos

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_28			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Forest Ave / Down (cont)

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_29			

Action/Comments

Inspector Comments: Revetments present.

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_30			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Repair site upstream of Hwy 99 / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_31			

Action/Comments

Inspector Comments: Scattered vegetation. The flow does not appear impeded.

Photo 1 of 1 : CH_2019_NA0060_12_31_20190710_00055.jpg



View looking upstream from Hwy 99 bridge, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Repair site upstream of Hwy 99 / Up (cont)

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_33			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c _ 2012_34			
Action/Comments				
Inspector Comments: The gabion wall repair is still intact and has no signs of damage. Riprap is visible and appears properly maintained under the bridge.				

Photo 1 of 3 : CH_2019_NA0060_12_34_20190710_00056.jpg



View of the gabion wall repair 300 yards upstream of the bridge at Highway 99, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Repair site upstream of Hwy 99 / Up (cont)

Rating **	A	Issue No.	34 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_34			

Action/Comments

Inspector Comments: The gabion wall repair is still intact and has no signs of damage. Riprap is visible and appears properly maintained under the bridge.

Photo 2 of 3 : CH_2019_NA0060_12_34_20190710_00057.jpg



View looking upstream of revetment at bridge abutment left bank, 2018.

Photo 3 of 3 : CH_2019_NA0060_12_34_20190710_00058.jpg



View of the revetment along the abutment of the bridge on the right bank looking upstream, 2019.

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_35			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Repair site upstream of Hwy 99 / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_36			
Action/Comments				
Inspector Comments: There is vegetation over the channel, the flow does not look to be impeded during high water.				

Photo 1 of 1 : CH_2019_NA0060_12_36_20190710_00059.jpg



View looking downstream from under the bridge, 2019.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_37			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_38			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Repair site upstream of Hwy 99 / Down (cont)

Rating **	A	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_39			

Action/Comments

Inspector Comments: Riprap is visible and appears properly maintained.

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_40			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Bruce Street / Up

Rating **	M	Issue No.	82	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2015_82			

Action/Comments

Inspector Comments: There is vegetation in the channel and it appears to potentially impede the flow.

Photo 1 of 1 : CH_2019_NA0060_12_82_20190710_00060.jpg



View of the channel from the bridge facing upstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Bruce Street / Up (cont)

Rating **	A	Issue No.	85	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_85			

Action/Comments

Inspector Comments: No shoaling or sedimentaion was observed at this location.

No Photos

Rating **	A	Issue No.	84	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_84			

Action/Comments

Inspector Comments: No erosion was observed at this location.

No Photos

Rating **	N	Issue No.	88	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_88			

Action/Comments

Inspector Comments: No riprap was observed.

Photo 1 of 2 : CH_2019_NA0060_12_88_20190710_00062.jpg



View of the abutment right bank, no revetment was observed at either side, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Bruce Street / Up (cont)

Rating **	N	Issue No.	88 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_88			
Action/Comments				
Inspector Comments: No riprap was observed.				

Photo 2 of 2 : CH_2019_NA0060_12_88_20190710_00063.jpg



View of the abutment left bank, no revetment was observed at either side, 2018.

Rating **	A	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2015_87			
Action/Comments				
Inspector Comments: No encroachments were observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Bruce Street / Down

Rating **	A	Issue No.	89	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2015_89			

Action/Comments

Inspector Comments: There is some vegetation on the banks, but the channel is clear and the flow does not appear to be impeded.

Photo 1 of 1 : CH_2019_NA0060_12_89_20190710_00061.jpg



View of the channel from the bridge facing downstream, 2019.

Rating **	A	Issue No.	90	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_90			

Action/Comments

Inspector Comments: No shoaling or sedimentation was observed.

No Photos

Rating **	A	Issue No.	91	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_91			

Action/Comments

Inspector Comments: No erosion was observed.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Bruce Street / Down (cont)

Rating **	N	Issue No.	92	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_92			

Action/Comments

Inspector Comments: No riprap was observed at this location.

No Photos

Rating **	A	Issue No.	93	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2015_93			

Action/Comments

Inspector Comments: No encroachments were observed.

No Photos

Check Point / View


Boucher St / Up

Rating **	M	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_41			

Action/Comments

Inspector Comments: There is vegetation in the channel and overhanging the channel, the flow could be impeded.

Photo 1 of 1 : CH_2019_NA0060_12_41_20190710_00064.jpg



View of the channel from the bridge facing upstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Boucher St / Up (cont)

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_42			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed.

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_43			

Action/Comments

Inspector Comments: No erosion observed.

No Photos

Rating **	N	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_44			

Action/Comments

Inspector Comments: There was no riprap observed at this site.

Photo 1 of 2 : CH_2019_NA0060_12_44_20190710_00065.jpg



View of the right bank abutment, no revetment present, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Boucher St / Up (cont)

Rating **	N	Issue No.	44 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_44			

Action/Comments

Inspector Comments: There was no riprap observed at this site.

Photo 2 of 2 : CH_2019_NA0060_12_44_20190710_00066.jpg



View of the left bank abutment, no revetment present, 2019.

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_45			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Boucher St / Down

Rating **	M	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_46			

Action/Comments

Inspector Comments: There is vegetation in the channel, overhanging the channel, and arundo. The flow does appear slightly impeded.

Photo 1 of 1 : CH_2019_NA0060_12_46_20190710_00067.jpg



View of the channel from the bridge facing downstream, 2019.

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_47			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed.

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_48			

Action/Comments

Inspector Comments: No erosion observed.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Boucher St / Down (cont)

Rating **	N	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_49			

Action/Comments

Inspector Comments: No riprap observed at this site.

No Photos

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_50			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Olive St / Up

Rating **	A	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_51			

Action/Comments

Inspector Comments: There is vegetation over the channel, it does not appear to impeded the flow.

Photo 1 of 1 : CH_2019_NA0060_12_51_20190710_00068.jpg



View of the channel from the bridge facing upstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View				
Olive St / Up (cont)				
Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_52			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	53	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_53			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	N	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_54			
Action/Comments				
Inspector Comments: No riprap observed at this site.				

Photo 1 of 2 : CH_2019_NA0060_12_54_20190710_00069.jpg



View of the right abutment, no revetment present, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View				
Olive St / Up (cont)				
Rating **	N	Issue No.	54 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c _ 2012_54			
Action/Comments				
Inspector Comments: No riprap observed at this site.				

Photo 2 of 2 : CH_2019_NA0060_12_54_20190710_00070.jpg



View of the left abutment, no revetment present, 2019.

Rating **	A	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_55			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Olive St / Down

Rating **	A	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_56			
Action/Comments				
Inspector Comments: There is vegetation over the channel, the flow does not appear impeded.				

Photo 1 of 1 : CH_2019_NA0060_12_56_20190710_00071.jpg



View of the channel from the bridge facing downstream, 2019.

Rating **	A	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_57			
Action/Comments				
Inspector Comments: There is minimal sedimentation in the channel, the flow does not appear impeded.				

No Photos

Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_58			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Olive St / Down (cont)

Rating **	N	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_59			

Action/Comments

Inspector Comments: No riprap observed at this site.

No Photos

Rating **	A	Issue No.	60	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_60			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.

No Photos

Check Point / View

Broadway St / Up

Rating **	M	Issue No.	61	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_61			

Action/Comments

Inspector Comments: Scattered obstructions and vegetation, and may impede the flow of the channel.

Photo 1 of 1 : CH_2019_NA0060_12_61_20190710_00072.jpg



View of the channel from the bridge facing upstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Broadway St / Up (cont)

Rating **	A	Issue No.	62	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_62			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed.

No Photos

Rating **	A	Issue No.	63	GPS Lat/Long
Issue Type +	Ob	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_63			

Action/Comments

Inspector Comments: No erosion observed.

No Photos

Rating **	N	Issue No.	64	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_64			

Action/Comments

Inspector Comments: No riprap observed.

Photo 1 of 2 : CH_2019_NA0060_12_64_20190710_00073.jpg



View of left abutment, no revetment observed, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Broadway St / Up (cont)

Rating **	N	Issue No.	64 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_64			

Action/Comments

Inspector Comments: No riprap observed.

Photo 2 of 2 : CH_2019_NA0060_12_64_20190710_00074.jpg



View of right abutment, no revetment observed, 2019.

Rating **	A	Issue No.	65	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_65			

Action/Comments

Inspector Comments: No encroachments observed at this site.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Broadway St / Down

Rating **	A	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_66			
Action/Comments				
Inspector Comments: There is vegetation over the channel, the flow does not appear impeded.				

Photo 1 of 1 : CH_2019_NA0060_12_66_20190710_00075.jpg



View of the channel from the bridge facing downstream, 2019.

Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_67			
Action/Comments				
Inspector Comments: No shoaling observed at this site.				

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_68			
Action/Comments				
Inspector Comments: No erosion observed at this site.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Broadway St / Down (cont)

Rating **	N	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_69			

Action/Comments

Inspector Comments: No riprap observed at this site.

No Photos

Rating **	A	Issue No.	70	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2013_70			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.

No Photos

Check Point / View

Ivy Street / Up

Rating **	A	Issue No.	94	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2015_94			

Action/Comments

Inspector Comments: Scattered obstructions and vegetation over channel, should not impede the flow of the channel.

Photo 1 of 1 : CH_2019_NA0060_12_94_20190710_00076.jpg



View of the channel from the bridge facing upstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Ivy Street / Up (cont)

Rating **	A	Issue No.	95	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_95			

Action/Comments

Inspector Comments: No shoaling or sedimentation was observed at this location.

No Photos

Rating **	A	Issue No.	96	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_96			

Action/Comments

Inspector Comments: No erosion was observed.

No Photos

Rating **	A	Issue No.	97	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_97			

Action/Comments

Inspector Comments: Sandbag revetment on right bank of abutment, no revetment on left bank and none needed.

Photo 1 of 2 : CH_2019_NA0060_12_97_20190710_00080.jpg



No revetment observed on the left bank abutment, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Ivy Street / Up (cont)

Rating **	A	Issue No.	97 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_97			
Action/Comments				
Inspector Comments: Sandbag revetment on right bank of abutment, no revetment on left bank and none needed.				

Photo 2 of 2 : CH_2019_NA0060_12_97_20190701_00041.jpg



View of sandbag revetment on right bank of abutment, 2017.

Rating **	A	Issue No.	98	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2015_98			
Action/Comments				
Inspector Comments: Trash, debris from homeless present within the channel easement, 2019				

Photo 1 of 1 : CH_2019_NA0060_12_98_20190710_00081.jpg



View of trash and debris from the homeless living under the bridge, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard


Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Ivy Street / Down

Rating **	M	Issue No.	99	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2015_99			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation, may impede the flow of the channel.				

Photo 1 of 1 : CH_2019_NA0060_12_99_20190710_00082.jpg



View of the channel from the bridge facing downstream, 2019.

Rating **	A	Issue No.	100	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_100			
Action/Comments				
Inspector Comments: No shoaling or sedimentaion was observed.				

No Photos

Rating **	A	Issue No.	101	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_101			
Action/Comments				
Inspector Comments: No erosion was observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Ivy Street / Down (cont)

Rating **	N	Issue No.	102	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_102			
Action/Comments				
Inspector Comments: No revetment observed.				

No Photos

Rating **	A	Issue No.	103	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2015_103			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.				

No Photos

Check Point / View

Walnut Street / Up

Rating **	A	Issue No.	104	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2015_104			
Action/Comments				
Inspector Comments: The channel appeared to be free of any vegetation that would impede the flow.				

Photo 1 of 1 : CH_2019_NA0060_12_104_20190710_00083.jpg



View of the channel from the bridge facing upstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View				
Walnut Street / Up (cont)				
Rating **	A	Issue No.	105	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_105			
Action/Comments				
Inspector Comments: No shoaling or sedimentation was observed.				

No Photos

Rating **	A	Issue No.	106	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_106			
Action/Comments				
Inspector Comments: No erosion was observed.				

No Photos

Rating **	A	Issue No.	107	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_107			
Action/Comments				
Inspector Comments: No riprap was observed				

Photo 1 of 2 : CH_2019_NA0060_12_107_20190710_00085.jpg



View of the right bank abutment, revetment present, 2018.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Walnut Street / Up (cont)

Rating **	A	Issue No.	107 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_107			

Action/Comments

Inspector Comments: No riprap was observed

Photo 2 of 2 : CH_2019_NA0060_12_107_20190710_00084.jpg



View of the left bank abutment, no revetment present, 2019.

Rating **	A	Issue No.	108	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2015_108			

Action/Comments

Inspector Comments: The channel appeared free of encroachments.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Walnut Street / Down

Rating **	A	Issue No.	109	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2015_109			

Action/Comments

Inspector Comments: The channel appeared free of any vegetation that would impede the flow. Although the Arundo should be removed before it chokes down the channel.

Photo 1 of 1 : CH_2019_NA0060_12_109_20190710_00086.jpg



View of the channel from the bridge facing upstream, 2019.

Rating **	A	Issue No.	110	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_110			

Action/Comments

Inspector Comments: No shoaling or sedimentation was observed.

No Photos

Rating **	A	Issue No.	111	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_111			

Action/Comments

Inspector Comments: No erosion was observed.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Walnut Street / Down (cont)

Rating **	N	Issue No.	112	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_112			

Action/Comments

Inspector Comments: No riprap was observed on left bank.

No Photos

Rating **	A	Issue No.	113	GPS Lat/Long
Issue Type +	Ma	Location *		39.718434 °
Category	Rivers, Channels & Designated Flood			-121.843512 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2015_113			

Action/Comments

Inspector Comments: The channel appeared free of encroachments.

No Photos

Check Point / View

Lone Pine Avenue / Up

Rating **	M	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_71			

Action/Comments

Inspector Comments: Scattered obstructions and vegetation, and may impede the flow of the channel.

Photo 1 of 1 : CH_2019_NA0060_12_71_20190710_00087.jpg



View of the channel from the bridge facing upstream, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Lone Pine Avenue / Up (cont)

Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_72			

Action/Comments

Inspector Comments: No shoaling observed at this site.

No Photos

Rating **	M	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_73			

Action/Comments

Inspector Comments: Some erosion observed at this site under the revetment.

Photo 1 of 1 : CH_2019_NA0060_12_73_20190710_00089.jpg



View of erosion under the sandbag revetment, 2019.

Rating **	A	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_74			

Action/Comments

Inspector Comments: Concrete filled sandbags used for riprap at bridge abutments on both sides.

Photo 1 of 2 : CH_2019_NA0060_12_74_20190710_00090.jpg



View of concrete sandbag revetment on the channels edge left bank, 2019.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Lone Pine Avenue / Up (cont)

Rating **	A	Issue No.	74 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_74			
Action/Comments				
Inspector Comments: Concrete filled sandbags used for riprap at bridge abutments on both sides.				

Photo 2 of 2 : CH_2019_NA0060_12_74_20190710_00091.jpg



View of concrete sandbag revetment on the channels edge right bank, 2019.

Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_75			
Action/Comments				
Inspector Comments: No encroachments observed at this site.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Lone Pine Avenue / Down

Rating **	A	Issue No.	76	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_76			
Action/Comments				
Inspector Comments: There is vegetation in the channel, the flow does not appear impeded.				

Photo 1 of 1 : CH_2019_NA0060_12_76_20190710_00092.jpg



View of the channel facing downstream from bridge, 2019.

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_77			
Action/Comments				
Inspector Comments: No shoaling observed at this site.				

No Photos

Rating **	A	Issue No.	78	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_78			
Action/Comments				
Inspector Comments: Some erosion observed at this site under the revetment.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/02/2019 07/02/2019	Sterling York

Check Point / View

Lone Pine Avenue / Down (cont)

Rating **	A	Issue No.	79	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_79			

Action/Comments

Inspector Comments: Concrete filled sandbags used for riprap at bridge abutments on both sides.

No Photos

Rating **	A	Issue No.	80	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_80			

Action/Comments

Inspector Comments: No encroachments observed at this site.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement